




PEST CONTROL EXPERTS




No.6, 1st Floor, Balaji Lodge Complex,
NH 46 Service Road(Chennai to Bangalore Highway),
Vellore - 632 004.Tamilnadu. Email:care@pestcontrolexpert.in
Cell: 9087200011 ; 9087200022




Facility Name & Address: IFF Fragrance Unit , srivity	Audited On: 09-04-2025
Audited By: SURESH KUMAR.V	
Client Contact Person Name: Mr. Siva (QC)	PC Experts Contact Person Name: SURESH KUMAR.V
Client Contact Person No: 7305428288	PC Experts Contact Person No: 8248672110




FACILITY SURROUNDING




In Our Audit your facility surrounded Thick Vegetation. Major threat for the surrounding is Flying insects, Rodents, Spiders, Snakes & Other Crawling insects.




Internal Premises			REVIEW DATE	COMPLETION DATE
1		Location	Scrap material movement near emergency door top side	
		Cleaning / sanitation & Housekeeping Issues	Nil	
		Structural Issue (Pest harbourages)	Wall crack noticed	
		Access Issues	Nil	
		Description of Pest Infestation	It is Serious Threat for Ants, lizard and crawling insects hiding	
		Any other observations	Nil	
		Preventive Action suggested to customer	Cracks should be closed with cement or white cement	
		Curative action from	We are instructed to Technician for Regular Monitoring.	




2		Location	Scrap movement area rooftop area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Roof top gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, lizards, crawling insects and ants		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with rain proof sheet or form sealent		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
3		Location	Scrap movement area shutter		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Shutter top gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizard, beetles and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with rubber beading		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
4		Location	Scrap movement area inside		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Wall crack observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizard, beetle May be hide		
		Any other observations	Nil		
		Preventive Action suggested to customer	Cracks and Crevices will be sealed with white cement or normal cement.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

5		Location	FG storage area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Windows mesh frame was opened condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, lizards, and crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Mesh frame should be closed		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
6		Location	FG storage area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Door to door frame between gap noticed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, ants, lizards and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with rubber beading or silicone sealant		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
7		Location	FG storage area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Rubber beading available but it's not fixed properly so that gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards, beetles and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Rubber beading should be placed properly without any gaps.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

8		Location	FG office area near emergency door top roof area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	FG office behind emergency door top roof side area gap noticed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetle, ants, lizards and crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with rubber beading or form sealant		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
9		Location	RM office near emergency door		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Door to door frame between gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, lizards and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Its should be closed with rubber beading or silicone sealant		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
10		Location	FG unloading shutter area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Wall to shutter frame gap noticed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, ants, lizards and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	It is should be closed with cement or silicone sealant.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

11		Location	RM loading area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Shutter frame bottom to floor Gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards, beetles and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with cement or rubber beading		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
12		Location	Fg area to preparation area between emergency door		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gap noticed from emergency door to frame		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles and ants and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with rubber beading or silicone sealant		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
External Premises				REVIEW DATE	COMPLETION DATE
13		Location	FG outside behind scrap movement area right side emergency door.		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Door bottom sealed with brush but it is now Gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, crawling insects, beetles,		
		Any other observations	Nil		
		Preventive Action suggested to customer	Once again it should be closed with brush permanently		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

14		Location	Scrap movement area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	At the time of inspection shutter was opened condition.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, snakes, lizards, crawling insects and rats may be get entry.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Once work completed in that particular area, shutter should be closed.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
15		Location	Loading and unloading area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Material lift area we observed the gaps		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards, snakes, rodents and other crawling insects.		
		Any other observations	Nil		
		Preventive Action suggested to customer	It should be closed with rubber beading		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
16		Location	Plant backside area		
		Cleaning / sanitation & Housekeeping Issues	Used materials kept on the Wall.		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	It is one of the pest hiding places.		
		Description of Pest Infestation	It is Serious Threat for Beetles, snakes rodents, lizards and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Don't allow the material near or on the wallside.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

17		Location	Power panel room outside area.		
		Cleaning / sanitation & Housekeeping Issues	Dry Honey comb not removed		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	It is critical to the service because of height above 25 feet.		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, lizards		
		Any other observations	Nil		
		Preventive Action suggested to customer	Dry Honey comb should be removed		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
18		Location	Lab 1st floor area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Some time door was opened condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants,rats, snakes, pats, lizard and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Whenever not used the doors, should be closed always		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
19		Location	Black side emergency door		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Emergency door bottom gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles and lizards		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with rubber beading or silicone sealant		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

Note: In General your all window mesh will be replaced all windows. Also in Processing area. Fly Killer Machine will be placed to Fly Catcher Machines

For Pest Control Experts


Authorized Signature.

Name: SURESH KUMAR.V

Designation: MANAGER

Emp.Code: 002

Phone Number: 8248672110



For M/s. IFF Fragrance Unit ,

Authorized Signature.

Name:

Designation:

Emp.Code:

Phone Number: