




PEST CONTROL EXPERTS





No.6, 1st Floor, Balaji Lodge Complex,
NH 46 Service Road(Chennai to Bangalore Highway),
Vellore - 632 004.Tamilnadu. Email:care@pestcontrolexpert.in
Cell: 9087200011 ; 9087200022





| | |
|--|--|
| Facility Name & Address: Levture wellness pvt ltd , Chittoor | Audited On: 30-05-2025 |
| Audited By: SURESH KUMAR.V | |
| Client Contact Person Name: Mr. Hiyath Abbas(QC) | PC Experts Contact Person Name: SURESH KUMAR.V |
| Client Contact Person No: 8400955576 | PC Experts Contact Person No: 8248672110 |





FACILITY SURROUNDING




Facility surrounding thick vegetation observed




| Internal Premises | | | | REVIEW DATE | COMPLETION DATE |
|-------------------|--|---|---|-------------|-----------------|
| 1 |  | Location | Hygiene Entry area | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Door surrounding gap observed | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, lizards, snakes, rat, flies and other crawling insects | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | It's should be closed with rubber beading | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |

| | | | | | |
|---|--|---|--|--|--|
| 2 |  | Location | Packing area | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Windows doors bottom gap observed | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, flies, lizards | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Gap should be closed with rubber beading | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| 3 |  | Location | Fruit packing area | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Mesh to mesh frame gap observed | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, lizards, flies & other crawling insects | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Gap should be closed with mesh | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| 4 |  | Location | Hygiene Entry area | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Fly catcher machine facia was not available | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, lizards, and flies | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Facia to be placed | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| 5 |  | Location | Fruit receiving area | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Door bottom gap observed | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, bettle, lizards, flies and other crawling insects | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Gap should be closed with rubber beading | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |

| | | | | | |
|---|--|---|--|--|--|
| 6 |  | Location | Fruit receiving area | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Gap observed between the door frame to door frame | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, lizards, flies and other crawling | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Gap should be closed with form sealent | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| 7 |  | Location | Fruit receiving area | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Nil | | |
| | | Access Issues | Fly catcher machine not worked | | |
| | | Description of Pest Infestation | It is Serious Threat for Beetles, flies, lizards | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Machine should be replaced | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| 8 |  | Location | Fruit receiving area | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Roof sheet to Wall sheet gap observed | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Beetles, flies, lizards | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Gap should be closed with rubber beading | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| 9 |  | Location | Fruit receiving area | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Roof top air exhaust purpose structure was placed,in that place gap observed | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Beetles, lizards, flies, Bird | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | That should be closed with mesh | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |

| | | | | | |
|----|--|---|---|--|--|
| 10 |  | Location | QA lab | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Exhaust fan area outside mesh frame gap observed | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, lizards, beetles, flies | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Gap should be closed with mesh | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| | | Location | Store room | | |
| 11 |  | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Door to door frame gap observed | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, snake, lizards, flies and other crawling insects | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Gap should be closed with rubber beading | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| | | Location | Maintenance room | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| 12 |  | Structural Issue (Pest harbourages) | Gap observed between the door to door frame | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for flies,Ants, beetles, lizards, rat and other crawling insects | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Gap should be closed with rubber beading | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| | | Location | Crate washing area | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Water running hole observed | | |
| 13 |  | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for rats, ants, lizards, snakes and other crawling insects | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Pipe hole should be closed with mesh | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| | | Location | Crate washing area | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Water running hole observed | | |
| | | Access Issues | Nil | | |

| | | | | | |
|----|--|---|---|--|--|
| 14 |  | Location | Crate washing area | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Wall to mesh frame gap observed | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Beetles, ants, lizards, flies and other crawling insects | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Gap should be closed with cement or rubber beading or form sealant | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| 15 |  | Location | Fruit packing area | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Hole observed | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, lizards, rat and other crawling insects | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Hole should be closed or what purpose made that should implement | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| 16 |  | Location | Fruit packing area | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Nil | | |
| | | Access Issues | Machine switched off condition | | |
| | | Description of Pest Infestation | It is Serious Threat for beetles, flies and other crawling insects | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Machine should be working condition | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |

| External Premises | | | | REVIEW DATE | COMPLETION DATE |
|--|--|---|--|-------------|-----------------|
| 17 |  | Location | Fruit receiving area | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Mesh to metal frame gap observed | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Beetles, flies, lizards | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Gap should be closed with mesh | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| 18 |  | Location | Fruit receiving area | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Mesh to frame gap observed | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for flies, lizards and other crawling insects | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Gap should be closed with mesh | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| 19 |  | Location | Hygiene Entry area | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Nil | | |
| | | Access Issues | At the time of inspection aircutain not worked | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, beetles, flies and lizards | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Aircutain should be working condition any time | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| Note: In General your all window mesh will be replaced all windows. Also in Processing area. Fly Killer Machine will be placed to Fly Catcher Machines | | | | | |
| For Pest Control Experts | | | For M/s. Levture wellness pvt ltd , | | |
| Authorized Signature. | | | Authorized Signature. | | |
| Name: SURESH KUMAR.V | | | Name: | | |
| Designation: MANAGER | | | Designation: | | |
| Emp.Code: 002 | | | Emp.Code: | | |
| Phone Number: 8248672110 | | | Phone Number: | | |