




PEST CONTROL EXPERTS




No.6, 1st Floor, Balaji Lodge Complex,
NH 46 Service Road(Chennai to Bangalore Highway),
Vellore - 632 004.Tamilnadu. Email:care@pestcontrolexpert.in
Cell: 9087200011 ; 9087200022




| | |
|--|--|
| Facility Name & Address: M/s. LCN Industries, Chittoor | Audited On: 15-09-2025 |
| Audited By: SURESH KUMAR.V | |
| Client Contact Person Name: Mr. Pandiyan (Manager) | PC Experts Contact Person Name: SURESH KUMAR.V |
| Client Contact Person No: 9493173163 | PC Experts Contact Person No: 8248672110 |




FACILITY SURROUNDING




Facility surrounding thick Vegetation observed




| External Premises | | | | REVIEW DATE | COMPLETION DATE |
|--|---|---|--|-------------|-----------------|
|  | Location | Main building outside entry area. | | | |
| | Cleaning / sanitation & Housekeeping Issues | Nil | | | |
| | Structural Issue (Pest harbourages) | All entry point we observed no PVC strips and Aircurtains | | | |
| | Access Issues | Nil | | | |
| | Description of Pest Infestation | It is Serious Threat for Beetles, Ants,lizards, flies, rodent and other crawling insect | | | |
| | Any other observations | Nil | | | |
| | Preventive Action suggested to customer | All entry points PVC strips and Aircurtains should be placed without any gaps. | | | |
| | Curative action from | We are instructed to Technician for Regular Monitoring. | | | |



| | | | | | |
|---|--|---|--|--|--|
| 1 |  | Location | AHU water and rain water outlet line | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | AHU pipe and rain water pipe and holes opened conditions. | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Cockroaches, rodents, snakes, ants, other crawling insect | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | All water pipe line should be closed with mesh or suitable lids. | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| 2 |  | Location | Main building outer area | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Wall to wall metal sheet between gaps observed. | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, beetles, flying insects, lizards and other crawling insect. | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Between gaps should be closed with form sealant without any gaps. | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| 3 |  | Location | Main building outer area (power cable line). | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Power cable trench to wall gap observed. | | |
| | | Access Issues | Cables between gaps observed. | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, lizards, flying insects and other crawling insect. | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Cable trench should be closed with form sealant or cement without any gaps. | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |

| | | | | | |
|---|--|---|--|--|--|
| 4 |  | Location | Building outer area (AHU line area) | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Gaps observed between the AHU to wall metal sheets. | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, lizards, spiders, flying insects and other crawling insect. | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Gaps should be closed with form sealent. | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| 5 |  | Location | Back side emergency door area. | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Emergency door surrounding lot of gaps observed | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, lizards, Cockroaches, flying insects and other crawling insect | | |
| | | Any other observations | Near cable switch box and wall between holes observed | | |
| | | Preventive Action suggested to customer | Gap should be closed with cement or form sealent. Cable hole should be closed with form or silicone sealent. | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| 6 |  | Location | Main emergency door (outside) | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Emergency door frame surrounding gaps noticed | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, beetles, lizards, flying insects and other crawling insect | | |
| | | Any other observations | Emergency Door bottom gap observed. | | |
| | | Preventive Action suggested to customer | Frame surroundings gap should be closed with cement or form sealent. Door bottom gap should be closed with rubber beading. | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |

| | | | | | |
|---|--|---|--|--|--|
| 7 |  | Location | Main building outer area | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Wall having hole, that we observed | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Beetles, Ants, rodent, lizards, snake and other crawling insect | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Hole should be closed with cement | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| 8 |  | Location | Vessels washing back side. | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Pipe was opened condition | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, Beetles, flying insects, lizards, cockroaches and other crawling insect | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Pipe should be closed with lid or pipe cap | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| 9 |  | Location | Main building outer (emergency door near) | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Cable line was opened conditions | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, beetles, lizards and other crawling insect | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Switch box should be placed without any gaps | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |

| | | | | | |
|----|--|---|--|--|--|
| 10 |  | Location | Main building FG area outer | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Door outer PVC strips and air curtains not fixed | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Beetles, ants, lizards, flying insects and other crawling insect | | |
| | | Any other observations | Door bottom gap observed. | | |
| | | Preventive Action suggested to customer | Door bottom gap should be closed with rubber beading. All doors entry points PVC strips and Aircurtains should be placed | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| 11 |  | Location | Main building back side (vessels washing back) | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Hole was observed on wall | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Beetles, lizards and other crawling insect | | |
| | | Any other observations | Nil | | |
| 12 |  | Location | Main building outer area (outer AHU area) | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Pipe surrounding gaps observed. All SS pipes surrounding holes observed | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, spider, lizards, beetles, flying insects and other crawling insect. | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | All pipe holes should be closed with form sealent | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |

| | | | | | |
|----|--|---|---|--|--|
| 13 |  | Location | Main building emergency door area. | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Door top left corner we observed the gaps. | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, beetles,lizards, flying insects and other crawling insect | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Gap should be closed with sheets without any gaps. | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| 14 |  | Location | Compound walls | | |
| | | Cleaning / sanitation & Housekeeping Issues | Tree branches fall down on the walls | | |
| | | Structural Issue (Pest harbourages) | Nil | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, lizards, snake, rats and other crawling insect | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Tree branch should be trimmed on regular basis. | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| 15 |  | Location | Back side gate. | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Gap noticed gate to gate frame and gate bottom gap observed. | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Ants, lizards, beetles, rodent, snake and other crawling insect. | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Gap should be closed with rubber beading metal sheet without any gaps. | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |

| | | | | | |
|---|---|---|--|--|--|
| 16 |  | Location | Main gate area | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Main gate bottom gaps noticed and gate to gate stem between gap observed. | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Beetles, rodent, lizards, snake and other crawling insect. | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Door bottom metal sheet or rubber beading should be placed. Stem to gate between gap should be closed with rubber beading. | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| 17 |  | Location | Back side gate near (left side ground level area) | | |
| | | Cleaning / sanitation & Housekeeping Issues | Nil | | |
| | | Structural Issue (Pest harbourages) | Gap observed | | |
| | | Access Issues | Nil | | |
| | | Description of Pest Infestation | It is Serious Threat for Beetles, cockroaches, snake, rodent, lizards, mosquitos, ants and other crawling insect | | |
| | | Any other observations | Nil | | |
| | | Preventive Action suggested to customer | Gap should be closed with cement | | |
| | | Curative action from | We are instructed to Technician for Regular Monitoring. | | |
| <p style="text-align: center;">Note: Fly catcher Machine 12 nos required.</p> | | | | | |
| For Pest Control Experts Authorized Signature. Name: SURESH KUMAR.V Designation: MANAGER Emp.Code: 002 Phone Number: 8248672110 | | | For M/s. M/s. LCN Industries, Authorized Signature. Name: Designation: Emp.Code: Phone Number: | | |

