




PEST CONTROL EXPERTS




No.6, 1st Floor, Balaji Lodge Complex,
NH 46 Service Road(Chennai to Bangalore Highway),
Vellore - 632 004.Tamilnadu. Email:care@pestcontrolexpert.in
Cell: 9087200011 ; 9087200022




Facility Name & Address: M/s. LCN Industries, Chittoor	Audited On: 15-09-2025
Audited By: SURESH KUMAR.V	
Client Contact Person Name: Mr. Pandiyan (Manager)	PC Experts Contact Person Name: SURESH KUMAR.V
Client Contact Person No: 9493173163	PC Experts Contact Person No: 8248672110




FACILITY SURROUNDING




Facility surrounding thick Vegetation observed




External Premises				REVIEW DATE	COMPLETION DATE
	Location	Main building outside entry area.			
	Cleaning / sanitation & Housekeeping Issues	Nil			
	Structural Issue (Pest harbourages)	All entry point we observed no PVC strips and Aircurtains			
	Access Issues	Nil			
	Description of Pest Infestation	It is Serious Threat for Beetles, Ants,lizards, flies, rodent and other crawling insect			
	Any other observations	Nil			
	Preventive Action suggested to customer	All entry points PVC strips and Aircurtains should be placed without any gaps.			
	Curative action from	We are instructed to Technician for Regular Monitoring.			




1		Location	AHU water and rain water outlet line		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	AHU pipe and rain water pipe and holes opened conditions.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Cockroaches, rodents, snakes, ants, other crawling insect		
		Any other observations	Nil		
		Preventive Action suggested to customer	All water pipe line should be closed with mesh or suitable lids.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
2		Location	Main building outer area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Wall to wall metal sheet between gaps observed.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, flying insects, lizards and other crawling insect.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Between gaps should be closed with form sealant without any gaps.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
3		Location	Main building outer area (power cable line).		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Power cable trench to wall gap observed.		
		Access Issues	Cables between gaps observed.		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards, flying insects and other crawling insect.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Cable trench should be closed with form sealant or cement without any gaps.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

4		Location	Building outer area (AHU line area)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gaps observed between the AHU to wall metal sheets.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards, spiders, flying insects and other crawling insect.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gaps should be closed with form sealent.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
5		Location	Back side emergency door area.		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Emergency door surrounding lot of gaps observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards, Cockroaches, flying insects and other crawling insect		
		Any other observations	Near cable switch box and wall between holes observed		
		Preventive Action suggested to customer	Gap should be closed with cement or form sealent. Cable hole should be closed with form or silicone sealent.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
6		Location	Main emergency door (outside)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Emergency door frame surrounding gaps noticed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, lizards, flying insects and other crawling insect		
		Any other observations	Emergency Door bottom gap observed.		
		Preventive Action suggested to customer	Frame surroundings gap should be closed with cement or form sealent. Door bottom gap should be closed with rubber beading.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

7		Location	Main building outer area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Wall having hole, that we observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, Ants, rodent, lizards, snake and other crawling insect		
		Any other observations	Nil		
		Preventive Action suggested to customer	Hole should be closed with cement		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
8		Location	Vessels washing back side.		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Pipe was opened condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, Beetles, flying insects, lizards, cockroaches and other crawling insect		
		Any other observations	Nil		
		Preventive Action suggested to customer	Pipe should be closed with lid or pipe cap		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
9		Location	Main building outer (emergency door near)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Cable line was opened conditions		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles, lizards and other crawling insect		
		Any other observations	Nil		
		Preventive Action suggested to customer	Switch box should be placed without any gaps		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

10		Location	Main building FG area outer		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Door outer PVC strips and air curtains not fixed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, ants, lizards, flying insects and other crawling insect		
		Any other observations	Door bottom gap observed.		
		Preventive Action suggested to customer	Door bottom gap should be closed with rubber beading. All doors entry points PVC strips and Aircurtains should be placed		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
11		Location	Main building back side (vessels washing back)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Hole was observed on wall		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, lizards and other crawling insect		
		Any other observations	Nil		
12		Location	Main building outer area (outer AHU area)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Pipe surrounding gaps observed. All SS pipes surrounding holes observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, spider, lizards, beetles, flying insects and other crawling insect.		
		Any other observations	Nil		
		Preventive Action suggested to customer	All pipe holes should be closed with form sealent		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

13		Location	Main building emergency door area.		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Door top left corner we observed the gaps.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetles,lizards, flying insects and other crawling insect		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with sheets without any gaps.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
14		Location	Compound walls		
		Cleaning / sanitation & Housekeeping Issues	Tree branches fall down on the walls		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards, snake, rats and other crawling insect		
		Any other observations	Nil		
		Preventive Action suggested to customer	Tree branch should be trimmed on regular basis.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
15		Location	Back side gate.		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gap noticed gate to gate frame and gate bottom gap observed.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, lizards, beetles, rodent, snake and other crawling insect.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with rubber beading metal sheet without any gaps.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

16		Location	Main gate area					
		Cleaning / sanitation & Housekeeping Issues	Nil					
		Structural Issue (Pest harbourages)	Main gate bottom gaps noticed and gate to gate stem between gap observed.					
		Access Issues	Nil					
		Description of Pest Infestation	It is Serious Threat for Beetles, rodent, lizards, snake and other crawling insect.					
		Any other observations	Nil					
		Preventive Action suggested to customer	Door bottom metal sheet or rubber beading should be placed. Stem to gate between gap should be closed with rubber beading.					
		Curative action from	We are instructed to Technician for Regular Monitoring.					
17		Location	Back side gate near (left side ground level area)					
		Cleaning / sanitation & Housekeeping Issues	Nil					
		Structural Issue (Pest harbourages)	Gap observed					
		Access Issues	Nil					
		Description of Pest Infestation	It is Serious Threat for Beetles, cockroaches, snake, rodent, lizards, mosquitos, ants and other crawling insect					
		Any other observations	Nil					
		Preventive Action suggested to customer	Gap should be closed with cement					
		Curative action from	We are instructed to Technician for Regular Monitoring.					
Note: Fly catcher Machine 12 nos required.								
For Pest Control Experts Authorized Signature. Name: SURESH KUMAR.V Designation: MANAGER Emp.Code: 002 Phone Number: 8248672110						For M/s. M/s. LCN Industries, Authorized Signature. Name: Designation: Emp.Code: Phone Number:		