




## PEST CONTROL EXPERTS




No.6, 1st Floor, Balaji Lodge Complex,  
NH 46 Service Road(Chennai to Bangalore Highway),  
Vellore - 632 004.Tamilnadu. Email:care@pestcontrolexpert.in  
Cell: 9087200011 ; 9087200022




Facility Name & Address: M/s. FROZEN TROPICAL PVT LTD , Chittoor	Audited On: 12-08-2025
Audited By: SURESH KUMAR.V	
Client Contact Person Name: Mr. Surendra (QC)	PC Experts Contact Person Name: SURESH KUMAR.V
Client Contact Person No: 7702187499	PC Experts Contact Person No: 8248672110



### FACILITY SURROUNDING

Facility Surrounding Thick vegetation observed

External Premises			REVIEW DATE	COMPLETION DATE
	Location	Electrical power cable line area		
	Cleaning / sanitation & Housekeeping Issues	Nil		
	Structural Issue (Pest harbourages)	Electrical power cable trench to wall sheet gap observed.		
	Access Issues	Nil		
	Description of Pest Infestation	It is Serious Threat for Beetles, lizards, snakes, monkey, flying insects and other crawling insects		
	Any other observations	Nil		
	Preventive Action suggested to customer	Gap should be closed with form and metal sheet without any gaps.		
	Curative action from	We are instructed to Technician for Regular Monitoring.		

1		Location	Main building Back side		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Metal sheet hole observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetle, flying insects, lizards and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Hole should be closed with form sealent		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
2		Location	Waste receiving conveyor line area		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Fruit waste receiving conveyor line and ss pipe to wall joint hole observed.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for beetle, flying insects, lizards and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with form sealent or cement		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
3		Location	Main building emergency door top side		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Ventilation mesh was damaged condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, flying insects, lizards and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	New mesh should be placed in all areas		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

4		Location	Main building front side		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Mesh was not fixed properly		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetle, flying insects, lizards and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Mesh should be placed without any gaps		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
5		Location	Main building Back side		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Mesh not properly fixed.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetle, lizards, flying insects and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Mesh should be placed without any gaps		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
6		Location	Main building emergency door top side		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Wall metal sheet to sheet gap observed		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, beetle, flying insects, lizards and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with cement or foam sealant or sheet		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

7		Location	Emergency door exit					
		Cleaning / sanitation & Housekeeping Issues	Nil					
		Structural Issue (Pest harbourages)	At the time of inspection we observed aircurtain not worked					
		Access Issues	Nil					
		Description of Pest Infestation	It is Serious Threat for Beetles, lizards, flying insects and other crawling insects.					
		Any other observations	Nil					
		Preventive Action suggested to customer	Aircurtain should be working condition					
		Curative action from	We are instructed to Technician for Regular Monitoring.					
<p><b>Note: In General your all window mesh will be replaced all windows. Also in Processing area. Fly Killer Machine will be placed to Fly Catcher Machines</b></p>								
<b>For Pest Control Experts</b> Authorized Signature. Name: SURESH KUMAR.V Designation: MANAGER Emp.Code: 002 Phone Number: 8248672110						<b>For M/s. M/s. FROZEN TROPICAL PVT LTD ,</b> Authorized Signature. Name: Designation: Emp.Code: Phone Number:		