




PEST CONTROL EXPERTS




No.6, 1st Floor, Balaji Lodge Complex,
NH 46 Service Road(Chennai to Bangalore Highway),
Vellore - 632 004.Tamilnadu. Email:care@pestcontrolexpert.in
Cell: 9087200011 ; 9087200022


Facility Name & Address: Kalis Sparkling Water Private Limited, , Sricity	Audited On: 20-08-2025
Audited By: MOHAMMED YOUNUS.A	
Client Contact Person Name: Ms.Shobana	PC Experts Contact Person Name: MOHAMMED YOUNUS.A
Client Contact Person No: 7680875163	PC Experts Contact Person No: 9087200011

FACILITY SURROUNDING

Thick Vegetation Noticed.

Internal Premises				REVIEW DATE	COMPLETION DATE
1		Location	Stamp Mold Area	23-09-2025	15-10-2025
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Around the pipeline gap noticed.		
		Access Issues	Nil		
		Description of Pest Infestation	It is serious threat for rodent lizard & crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Around the Pipeline Gap will be closed with cement mortar or Foam Sealant.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

2		Location	Stamp Molding Area	17-09-2025	15-10-2025
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gap noticed between channel and sheet		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threats for Flies, Lizards & Aphids		
		Any other observations	Nil		
		Preventive Action suggested to customer	Around the channel Gap will be closed with cement mortar or Foam Sealant.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
3		Location	Filler Area	16-09-2025	15-10-2025
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Gap observed Roof Sheet Covings		
		Access Issues	Nil		
		Description of Pest Infestation	It is a serious threat for Flying insects, lizards and spiders		
		Any other observations	Nil		
		Preventive Action suggested to customer	Around the sheet Gap will be closed with cement mortar or Foam Sealant.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
4		Location	FILLING AREA	16-09-2025	15-10-2025
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	PVC Strips Damaged.		
		Access Issues	Nil		
		Description of Pest Infestation	It is serious threat for flies		
		Any other observations	Nil		
		Preventive Action suggested to customer	PVC strips must be replaced		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

5		Location	Labelling Area	16-09-2025	15-10-2025
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	The serious threat of flies and rodent entry		
		Any other observations	Windows are kept open.		
		Preventive Action suggested to customer	Permanent fixture of Mesh in outside windows		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
<p>Note: All over the facility coving floor crack noticed. Out of the Seven fly catcher machines, three are under repair. There are gaps in the exhaust surroundings throughout the factory.</p>					
For Pest Control Experts Authorized Signature. Name: MOHAMMED YOUNUS.A Designation: MANAGER Emp.Code: 001 Phone Number: 9087200011			For M/s. Kalis Sparkling Water Private Limited, , Authorized Signature. Name: Designation: Emp.Code: Phone Number:		

