PEST CONTROL EXPERTS
No.6, 1st Floor, Balaji Lodge Complex,
NH 46 Service Road(Chennai to Bangalore Highway),
Vellore - 632 004.Tamilnadu. Email:care@pestcontrolexpert.in
Cell: 9087200011 ; 90872000022

Facility Name & Address: M/s. plastic omnium Auto Inergy Pvt Ltd , Lalapet, Ranipet	**Audited On: 25-08-2025**
Audited By: SURESH KUMAR.V	
Client Contact Person Name: Ms.Sudha (Asst HR)	**PC Experts Contact Person Name: SURESH KUMAR.V**
Client Contact Person No: 9655249232	**PC Experts Contact Person No: 8248672110**

FACILITY SURROUNDING

Facilities Surrounding Thick vegetation observed.

External Premises			REVIEW DATE	COMPLETION DATE
	Location	Main buliding back side (emergency door)		
	Cleaning / sanitation & Housekeeping Issues	Nil		
	Structural Issue (Pest harbourages)	Door was opened condition		
	Access Issues	Nil		
	Description of Pest Infestation	It is Serious Threat for Rodent, lizards, snakes and other crawling insects		
	Any other observations	Nil		
	Preventive Action suggested to customer	All doors should be closed without any gaps		
	Curative action from	We are instructed to Technician for Regular Monitoring.		

1		Location	Back side compound wall area		
		Cleaning / sanitation & Housekeeping Issues	Thick vegetation observed		
		Structural Issue (Pest harbourages)	Compound wall having Holes		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for snakes, rodent and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Holes should be closed with cement. Vegetation should be clean on regular basis.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
2		Location	Main buliding back side (Emergency exit door)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Door was Opened Condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Monkey, snakes, Rodents and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Door should be closed without any gaps		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
3		Location	Two wheeler parking area		
		Cleaning / sanitation & Housekeeping Issues	Lot Thick vegetation observed		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Ants, mosquitos, lizards, snakes, rodent and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Thick vegetation should be clean on regular basis		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

4		Location	Parking area		
		Cleaning / sanitation & Housekeeping Issues	Thick vegetation observed		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, ants, mosquitos, rodent, snakes and other crawling insects.		
		Any other observations	Nil		
		Preventive Action suggested to customer	Thick vegetation should be clean on regular basis		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
5		Location	Two wheeler parking area (near godown)		
		Cleaning / sanitation & Housekeeping Issues	Un used materials kept near by godown		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for snakes, Rodent and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Don't store the materials near by building.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
6		Location	Godown back side		
		Cleaning / sanitation & Housekeeping Issues	Unused material kept near by building and Thick vegetation observed		
		Structural Issue (Pest harbourages)	Old godown wall to wall metal sheet having gaps.		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for Beetles, mosquitos, snakes, rodents and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Gap should be closed with cement or foam sealent. Don't allow the materials near by the building out side. Thick vegetation should be clean on regular basis.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

7		Location	Main buliding back side (steps area under)		
		Cleaning / sanitation & Housekeeping Issues	We observed the rodent borrows		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for rodent and snakes		
		Any other observations	Nil		
		Preventive Action suggested to customer	Steps under borrows should closed with cement		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
8		Location	Waste dumping area		
		Cleaning / sanitation & Housekeeping Issues	Waste should be clean on regular basis		
		Structural Issue (Pest harbourages)	Waste dumping area was opened condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for rodent, snakes and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Waste should be clean on regular basis.		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
9		Location	Main buliding back side		
		Cleaning / sanitation & Housekeeping Issues	Thick vegetation observed		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Used materials kept near the building		
		Description of Pest Infestation	It is Serious Threat for Rodent,. snakes		
		Any other observations	Nil		
		Preventive Action suggested to customer	Don't allow the materials near by the building wall		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
10		Location	Back side compound wall area		
		Cleaning / sanitation & Housekeeping Issues	Lot of water stagnated		
		Structural Issue (Pest harbourages)	Nil		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for mosquitos, other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Don't allow the stagnating water in factory premises		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

11		Location	Ware House (Entrance area)		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Main entrance was opened condition		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for snakes, rodents and other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Shutters should be closed condition		
		Curative action from	We are instructed to Technician for Regular Monitoring.		
12		Location	Ware House back side		
		Cleaning / sanitation & Housekeeping Issues	Nil		
		Structural Issue (Pest harbourages)	Ware House Back side floor concrete not available		
		Access Issues	Nil		
		Description of Pest Infestation	It is Serious Threat for mosquitos, rodent, snakes other crawling insects		
		Any other observations	Nil		
		Preventive Action suggested to customer	Ware House back side floor concrete should be placed upto 2 feet		
		Curative action from	We are instructed to Technician for Regular Monitoring.		

Note: In General your all window mesh will be replaced all windows. Also in Processing area. Fly Killer Machine will be placed to Fly Catcher Machines

For Pest Control Experts

Authorized Signature.



Name: SURESH KUMAR.V

Designation: MANAGER

Emp.Code: 002

Phone Number: 8248672110

For M/s. M/s. plastic omnium Auto Inergy Pvt Ltd ,

Authorized Signature.

Name:

Designation:

Emp.Code:

Phone Number: